

METER REPLACEMENT REPORT UNDER UMIAM RURAL SUB-DIVISION CONDUCTED ON THE 21st OCTOBER, 2025.

SL NO	CONSUMER NUMBER	SL No	NAME OF CONSUMER	ADDRESS	DT	CONTRACT DEMAND (KVA)	M/F	DATE OF METER REPLACEMENT	OLD METER NO.	NEW METER NO.	CATEGORY	READING FOR NEW METER						Old Seal	New Seal	Remark
												KWH	KVAH	KVA	V1	V2	V3			
1	1000345402	1	The Director, Nepa	Umiar		250	60	21.10.25	IN4000454	MS5004643	BS	0	0	0	239	241	241	TTB-0008681	TTB-11122176	<u>Old Meter found defected & therefore replaced with new Meter No. MS5004643. Use Airtel simcard no: 0621 ID 899116099001 8237621U</u>
2	1000198099	2	Mawsiatkhnar PHC	Mawsiatkhnar, Umiar		15	10	21.10.25	MS5003511	MS5004793	DLT	0	0	0	237	239	237	NA	NA	<u>Old Meter Display found defected & therefore replaced with new Meter No. MS5004793. Use JIO simcard no: 8991 8650 5070 6001 5835</u>
		3	MELINDIA NONGBRI	LUMRIT		1	1	21.10.25	4649575A	11122180	BPL(M)	0			234			NA	NA	<u>Old Meter found defected & therefore replaced with new 1Ph Smart Meter No. 11122180. Use JIO simcard no: 8991 8650 4060 0069 6525</u>

(F.L KYNSHI)
 ASSISTANT EXECUTIVE ENGINEER
 Investigation & Enforcement, Ribhoi Distribution Circle
 MePDCL,Umiar