

Report: I have inspected the spot of YH97 on 31/10/12. As per Consumer Complaint & Abnormal Demand, found & observed that Abnormal Demand to wrong Mct when Mechanical to an meter replaced time. Actual YH98 Mechanical meter replaced, YH97 an meter not replaced at spot. This is for kind information for wrong Mct Case.
Meter Details

YH 97

L66, 5X30A

SL - BD0098839

ER - 3409.

YH 98

LAT

S-30A

SL - A9567424

ER - 141.

 31/10/12

J. E. Brown

BECON.