

ghalaya Energy Power Distribution Corporation Limited TEST REPORT

This is to certify that repaired/renewed/additional/new electric installation at the premises of

SMT HIRTIMON PYNAROPPE

(Please leave one block between name & surname)

(Full Name)

MANPAT CIRCLE II

(Address)

is duly completed, tested and is ready for your Engineer to test and connect on your main line.

1 The load has been arranged as follows :-

Details of Load	Wattage of each item							Total watt of all 3 phases
		No. of points	Total Watt	No. of points	Total Watt	No. of points	Total Watt	
1. Light points (i) Fluorescent (ii) Incandescent (iii) CFL (iv) Halogen (v) Others	9 W	5 Nos	45 W					
2. Fan points								
3. Plug points (3-pin) (i) 6 Amps (ii) 16 Amps	100 W 1000 W	2 Nos 1 No	200 W 1000 W					
4. Electrical gadgets (i) Water Heater (Geyser) (ii) Refrigerator (iii) Air Conditioner (iv) Others								
5. Welding Transformer								
6. Motor								
Total			1245 W					
In case of load enhancement Existing load (in watts)								
Total load in premises (in watts)			1245 W	Say	2 kVA			

Notes :-

- Details of any apparatus (other than the above mentioned) should be given.
- Rating of capacitor used in Induction Motor and Welding Transformer (Test report of capacitor is to be enclosed).

KVAR