

Meghalaya Power Distribution Corporation Limited

TEST REPORT

This is to certify that/repaired/additional/ enhancement/ reduction/new electric installation at the premises of

LUCYNA MARY LYNQDOH

(Please leave one block between name & surname)

(Full Name)

DIENGIONG NEIGRIHAMS

(Address)

is duly completed, tested and is ready for your Engineer to test and connect on your main line.

I. The load has been arranged as follows :-

Details of Load	Wattage of each item	Phase - 1		Phase - 2		Phase - 3		Total watt of all 3 phases
		No. of points	Total watt	No. of points	Total watt	No. of points	Total watt	
1. Light points								
(i) Fluorescent	20	5	100					
(ii) Incandescent								
(iii) CFL LED Bulb	7	20	180					
(iv) Halogen								
(v) Others								
2. Fan points								
3. Plugs points (3-pins)								
(i) 6 Amps	100	5	500					
(ii) 16amps	1000	1	1000					
4. Electrical gadget								
(i) Water Heater (Geyser)								
(ii) Refrigerator								
(iii) Air Conditioner								
(iv) Others								
5. Welding Transformer								
6. Motor								
Total			1780					
In case of load enhancement Existing load (in watt)								
Total load in the premises (in watt)								