

Meghalaya Energy Power Distribution Corporation Limited

TEST REPORT

This is to certify that repaired/renewed/additional/new electric installation at the premises of

JRIAL KHARSHONG

(Please leave one blank between name & surname)

(Full Name)

MAWPDANG EKH DIST

(Address)

is duly completed, tested and is ready for your Engineer to test and connect on your main line.

1 The load has been arranged as follows :-

Details of Load	Wattage of each item							Total watt of all 3 phases
		No. of points	Total Watt	No. of points	Total Watt	No. of points	Total Watt	
1 Light points								
(i) Fluorescent								
(ii) Incandescent								
(iii) CFL								
(iv) Halogen								
(v) Others								
(vi) LED (GWB)	9w	3	27w					
2 Fan points								
3 Plug points (3-pin)								
(i) 6 Amps	100	2	200w					
(ii) 16 Amps								
4 Electrical gadgets								
(i) Water Heater (Geyser)								
(ii) Refrigerator								
(iii) Air Conditioner								
(iv) Others								
5 Welding Transformer								
6 Motor								
Total			227w					
In case of load enhancement								
Existing load (in watts)								
Total load in premises (in watts)								

Notes :-

- Details of any apparatus (other than the above mentioned) should be given.
- Rating of capacitor used in Induction Motor and Welding Transformer (Test report of capacitor is to be enclosed)

KVAR