

Meghalaya Energy Corporation Limited

K-LF

TEST REPORT

This is to certify that repaired/renewed/additional/new electric installation at the premises of

SMT CHALISTAR SUTNGA

(Full Name)

(Please leave one block between name & surname)

ITSHYRWAT SHILLONG

(Address)

is duly completed, tested and is ready for your Engineer to test and connect on your main line.

1. The load has been arranged as follows:-

Details of Load	Wattage of each item	Phase - I		Phase - 2		Phase - 3		Total watt of all 3 phases
		No. of points	Total wart	No. of points	Total wart	No. of points	Total wart	
1. Light points (i) Fluorescent (ii) Incandescent (iii) CFL LED (iv) Halogen (v) Others	20	10	200					
2. Fan points								
3. Plug points (3-pin) (i) 6 Amps - - (ii) 16 Amps - -	100 1000	4 1	400 1000					
4. Electrical gadgets (i) Water Heater (geyser) (ii) Refrigerator (iii) Air Conditioner (iv) Others								
5. Welding Transformer								
6. Motor								
Total			1600					
In case of load enhancement Existing load (in watts)								
Total load in the premises (in watts)			1600					

Notes:-

- (a) Details of any apparatus (other than the above mentioned) should be given.
 (b) Rating of capacitor used in Induction Motor and Welding Transformer
 (Test Report of capacitor is to be enclosed)

KVAR