

Meghalaya Power Distribution Corporation Limited  
TEST REPORT

This is to certify that/repaired/additional/ enhancement/ reduction/new electric installation at the premises of

LYDIA S BAMON

(Please leave one block between name & surname)

(Full Name)

MAWPAT CIRCLE-I

(Address)

is duly completed, tested and is ready for your Engineer to test and connect on your main line.

I. The load has been arranged as follows :-

Details of Load	Wattage of each item	Phase - 1		Phase - 2		Phase - 3		Total watt of all 3 phases
		No. of points	Total watt	No. of points	Total watt	No. of points	Total watt	
1. Light points (i) Fluorescent (ii) Incandescent (iii) CFL/LED Bulb (iv) Halogen (v) Others	15	20	300					
2. Fan points								
3. Plugs points (3-pins) (i) 6 Amps (ii) 16amps	100 1000	5 2	500 2000					
4. Electrical gadget (i) Water Heater (Geyser) (ii) Refrigerator (iii) Air Conditioner (iv) Others								
5. Welding Transformer								
6. Motor								
Total			2800					
In case of load enhancement Existing load (in watt)			1200					
Total load in the premises (in watt)			Say 3000					