Meghalaya Power Distribution Corporation Limited TEST REPORT

This is to certify that/repaired/additional/ enhancement/ reduction/new electric installation at the premises of

			-								
BANSKHE	MCF	149		3 4	NN	AH					
	(Please le	ave one	block	betwe	en nai	me & si	ırnaı	ne)			
(Full Name)											
5 AR DIT											
(Address)				ì							

is duly completed, tested and is ready for your Engineer to test and connect on your main line.

I. The load has been arranged as follows:-

Details	Phase -	- 1	Phase -	- 2	Phase	Total watt of		
of Load	each item	No. of points	Total watt	No. of points	Total watt	No. of points	Total watt	all 3 phases
gadget (i) Water Heater (Conver)		Elect 1	10001					
Total		1000	walls					
In case of load en Existing load (in		1000) walt	}				
Total load in the watt)	premises (in	J.K.						