IVISION, Sub-Div...

Meghalaya Power Distribution Corporation Limited

TEST REPORT

his is to certify that/repaired/additional/ enhancement/ reduction/new electric installation at the premises of

GURDAN KHARUMWUID

(Please leave one block between name & surname)

Name)

ANPDANG MAWMYLLIEM

dress)

ully completed, tested and is ready for your Engineer to test and connect on your main line.

The load has been arranged as follows :-

Details of Load	Wattage of each item	Phase - 1		Phase - 2		Phase - 3		Total watt of all 3 phases
		No. of points	Total watt	No. of points	Total watt	No. of points	Total watt	
1. Light points								
(i) Fluorescent								
(ii) Led Incandescent	20 w	10	200w.					
(iii) CFL/LED Bulb Led	10 w	20	100w.					
(iv) Halogen								
(v) Others —	60 w	2	120w.					
2. Fan points								
3. Plugs points (3-pins)								
(i) 6 Amps —	100 w	5	500w					
(ii) 16amps —	1000w	1	1000w					
4. Electrical gadget								
(i) Water Heater (Geyser)								
(ii) Refrigerator								
(iii) Air Conditioner								
(iv) Others								
5. Welding Transformer								
6. Motor								
Total			1920		—		—	1920w
In case of load enhancement Existing load (in watt)								1kw
Total load in the premises (in watt)								3kw