

Meghalaya Power Distribution Corporation Limited

TEST REPORT

This is to certify that/repaired/additional/ enhancement/ reduction/new electric installation at the premises of

ALISHA SYNNAH

(Full Name)

(Please leave one block between name & surname)

MAWPDANG

(Address)

is duly completed, tested and is ready for your Engineer to test and connect on your main line.

1. The load has been arranged as follows :-

Details of Load	Wattage of each item	Phase - 1		Phase - 2		Phase - 3		Total watt of all 3 phases
		No. of points	Total watt	No. of points	Total watt	No. of points	Total watt	
1. Light points (i) Fluorescent (ii) Incandescent (iii) CFL/LED Bulb (iv) Halogen (v) Others								
2. Fan points								
3. Plugs points (3-pins) (i) 5 Amps (ii) 16amps	1000 W	2	2000 watt					
4. Electrical gadget (i) Water Heater (Geyser) (ii) Refrigerator (iii) Air Conditioner (iv) Others								
5. Welding Transformer								
6. Motor								
Total			2000 watt					
In case of load enhancement Existing load (in watt)			1000 watt					
Total load in the premises (in watt)			3000 watt					

I Note:-

(a) Detail of any apparatus (other than the above mentioned) should be given.