

Meghalaya Energy Corporation Limited

TEST REPORT

This is to certify that repaired/renewed/additional/new electric installation at the premises of

SHRI SMAN KURBAH

(Please leave one block between name & surname)

(Full Name)

DIENGPA SOH

(Address)

is duly completed, tested and is ready for your Engineer to test and connect on your main line.


1. The load has been arranged as follows:-

Details of Load	Wattage of each item	Phase - 1		Phase - 2		Phase - 3		Total watt of all 3 phases
		No. of points	Total watt	No. of points	Total watt	No. of points	Total watt	
1. Light points (i) Fluorescent (ii) Incandescent (iii) CFL (iv) Halogen (v) Others	100	4	400					
2. Fan points								
3. Plug points (3-pin) (i) 6 Amps (ii) 16 Amps	100 1000	4 1	400 1000					
4. Electrical gadgets (i) Electric Fan (ii) Electric Iron (iii) Electric Heater (iv) Refrigerator (v) Air Conditioner (vi) Others								
5. Welding Transformer								
6. Motor								
Total			1800					
In case of load enhancement Existing load (in watts)								
Total load in the premises (in watts)								

Notes:-

(a) Details of any apparatus (other than the above mentioned) should be given.

(b) Rating of capacitor used in Induction Motor and Welding Transformer (Test report of capacitor is to be enclosed).



KVAR