

Meghalaya Energy Power Distribution Corporation Limited

TEST REPORT

This is to certify that repaired/renewed/additional/new electric installation at the premises of

S H A L O A L I N S W E R .

(Please leave one block between name & surname)

(Full Name)

J A R O I T

(Address)

is duly completed, tested and is ready for your Engineer to test and connect on your main-line.

1. The load has been arranged as follows :-

Details of Load	Wattage of each item	No. of points		Total Watt		No. of points		Total Watt		Total watt of all 3 phases
		No. of points	Total Watt	No. of points	Total Watt	No. of points	Total Watt			
1. Light points	<i>Existing load</i> <i>P/P 2x1000W</i>				<i>1kw</i>					
(i) Fluorescent										
(ii) Incandescent					<i>2000W</i>					
(iii) CFL										
(iv) Halogen						<i>2000W</i>				
(v) Others										
2. Fan points										
3. Plug points (3-pin)										
(i) 6 Amps										
(ii) 16 Amps										
4. Electrical gadgets										
(i) Water Heater (Geyser)										
(ii) Refrigerator										
(iii) Air Conditioner										
(iv) Others										
5. Welding Transformer										
6. Motor										
Total					<i>3kw</i>					
In case of load enhancement Existing load (in watts)					<i>1kw</i>					
Total load in premises (in watts)					<i>3kw</i>					

Notes :-

- (a) Details of any apparatus (other than the above mentioned) should be given.
- (b) Rating of capacitor used in Induction Motor and Welding Transformer (Test report of capacitor is to be enclosed).

KVAR