Meghalaya Power Distribution Corporation Limited TEST REPORT

This is to certify that/repaired/additional/ enhancement/ reduction/new electric installation at the premises of

SHRI	ASIC	NS	TIA	R	MA	IRIB	DH	Ц		
	(F	lease lea	ve one	block	between	name 8	k surna	me)		
(Full Name)										
TYNRI	NG									
(Address)				1						

is duly completed, tested and is ready for your Engineer to test and connect on your main line.

I. The load has been arranged as follows:-

Details of Load	Wattage of	Phase - 1		Phase -	2	Phase	- 3	Total watt of	
	each item	No. of points	Total watt	No. of points	Total watt	No. of points	Total watt	all 3 phases	
1. Light points (i) Fluorescent (ii)	loo	4	400				2 H 01	791 g W	
Incandescent (iii) CFL/LED Bulb (iv) Halogen			,	,		Chienal V	Tel us		
(v) Others 2. Fan points				,		3 (1)			
3. Plugs points (3-pins) (i) 6 Amps (ii) 16amps	100	4	400	e e					
4. Electrical gadget (i) Water Heater (Geyser) (ii) Refrigerator (iii) Air Conditioner				10					
(iv) Others5. WeldingTransformer									
6. Motor	- 12 12 v								
Total		800		41.4			3-1600	i, e st	
In case of load e Existing load (in	watt)	l	000						
Total load in the watt)	premises (in		800	kwt					