

Meghalaya Energy Corporation Limited

TEST REPORT

This is to certify that repaired/renewed/additional/new electric installation at the premises of

SMTI PYNHUNLANG BINA

(Please leave one block between name & surname)

(Full Name)

DIENGPASOH

(Address)

is duly completed, tested and is ready for your Engineer to test and connect on your main line.

1. The load has been arranged as follows:-

Details of Load	Wattage of each item	Phase - 1		Phase - 2		Phase - 3		Total watt of all 3 phases
		No. of points	Total watt	No. of points	Total watt	No. of points	Total watt	
1. Light points (i) Fluorescent (ii) Incandescent (iii) CFL (iv) Halogen (v) Others	100	4	400					
2. Fan points								
3. Plug points (3-pin) (i) 6 Amps (ii) 16 Amps	100	4	400					
4. Electrical gadgets (i) Electric fan (ii) Electric iron (iii) Refrigerator (iv) Air Conditioner (v) Others								
5. Welding Transformer								
6. Motor								
Total			800					
In case of load enhancement			+ 1000					
Existing load (in watts)			1800					
Total load in the premises (in watts)					kw			

than the above mentioned) should be given.