ate his caused and the sur

## Meghalaya Power Distribution Corporation Limited

## TEST REPORT

This is to certify that/repaired/additional/ enhancement/ reduction/new electric installation at the premises of

## SHRI PRINCELY KHARKOWADR (Please leave one block between name & surname)

(Full Name)

M A W P A T C I R C L E - M S H I LLONG - E Z (Address)

is duly completed, tested and is ready for your Engineer to test and connect on your main line.

I. The load has been arranged as follows:-

	Wattage of each item	Phase - 1		Phase - 2		Phase - 3		Total watt of
of Load		No. of points	Total watt	No. of points	Total watt	No. of points	Total watt	all 3 phases
1. Light points (i) Fluorescent (ii) Incandescent (iii) CFL/LED Bulb (iv) Halogen (v) Others 2. Fan points	20	15	300					
3. Plugs points (3-pins) (i) 6 Amps (ii) 16amps	r00 l000	5	500					
4. Electrical gadget (i) Water	Mid ITS	ions ions	**					
Heater (Geyser) (ii) Refrigerator (iii) Air Conditioner (iv) Others	Aport in a							
5. Welding Transformer								
6. Motor					e Central			
Total		7	1800 W	t			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
In case of load en Existing load (in v	vatt)		2KW					
Total load in the	premises (in	Tin.	•					