net store

Meghalaya Power Distribution Corporation Limited TEST REPORT

This is to certify that/repaired/additional/ enhancement/ reduction/new electric installation at the premises of

Thorestillan	1012 101 (10)	KI (al I I I		
(Please lear	ve one block betwe	en name & surnam	e)	And the second second
(Full Name)				
NONGHALI				
(Address)				

is duly completed, tested and is ready for your Engineer to test and connect on your main line.

I. The load has been arranged as follows:-

Details	Wattage of	Phase -	Phase - 1		Phase = 2		Phase = 8	
of Load cach item	No. of points	Total watt	No. of points	Total watt	No. of points	Total watt	watt of all 3 phases	
1. Light points (i) Fluorescent (ii) Incandescent (iii) CFL/LED Bulb (iv) Halogen (v) Others	9 w	50NB)	90w	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	a masaning da and a la delimination of the del			
2. Fan points	À			Aff				,
3. Plugs points (3-pins) (i) 6 Amps (ii) 16amps	100 bit	Inos	2004	E CONTRACTOR OF STREET				
4. Electrical gadget (i) Water Heater (Geyser) (ii) Refrigerator (iii) Air Conditioner (iv) Others	AVII)					
5. Welding Transformer 6. Motor								
Total			1290	watt				
Existing load	l enhancement (in watt) the premises (in			Day	3			