

MEGHALAYA ENERGY CORPORATION LTD

TEST REPORT.

This is to certify that repaired/renewed/additional/new electric installation at the premises of

J D O L I S P A R L O N G

(Please leave one block between name & surname)

(Full name)

M A W E R M A N P A T S H I L L O N G

(Address)

is duly completed, tested and is ready for your Engineer to test and connect on your main line.

1. The load has been arranged as follows :-

Details of Load	Wattage of each item	Phasi - 1		Phasi - 2		Phasi - 3		Total Watt of all 3 phases
1. Light Points								
(i) Fluorescent	20 w	8pc	100w					
(ii) Incandescent	100 w	3pc	300w					
(iii) CFL	9 w	10pc	90w					
(iv) Halogen								
(v) Others								
2. Fan Points								
3. Plug Points (3-pin)	100 w	1 no	100w					
(i) 6Amps	100w	3pc	300w					
(ii) 16Amps	1000w	2pc	2000w					
4. Electrical gadgets								
(i) Water Heater (geyser)								
(ii) Refrigerator								
(iii) Air Conditioner								
(iv) Other								
5. Welding Transformer								
6. Motor								
Total			2890w					
In case of load enhancement			or 3kw					
Existing load (in watts)								
Total load in the premises (in watts)								

Notes :-

- (a) Details of any apparatus (other than the above mentioned) should be given.
- (b) Rating of capacitor used in Induction Motor and Welding Transformer (Test report of capacitor is to be enclosed)



KVAR