f the Corporation

MEGHALAYA ENERGY CORPORATION LIMITED TEST REPORT (LT SUPPLY)

The			
_	nat repaired / re	enewed / additional / new electric installation at the premises of	
(Full Name)			
14 14 15 K T 18	(Please le	ave one block between name & sumame)	
(Address)	300	· ·	HZUS
TYNRI	NG PI	DENGSHONONG EMST KHAST	1,-
		MEGHALAYA - 793012	

is duly completed, tested and is ready for your authorized representatives to test and connect on your main line.

I. The load has been arranged as follows:-

Details of Load	Wattage	Phase- I		Phase- II		Phase- III		Total watt	
Details of Detail	of each item	No. of points	Total watt	No. of points	Total watt	No. of points	Total watt	of all 3 phases	
									1. Light points
(i) Fluorescent	(130		÷	5.		200		
(ii) Incandescent		A A C	1006	K. 37 .	HERET LL	A CONTRACTOR		y	
(iii) CFL	140000000000000000000000000000000000000	I george was	- 4	LA PART	The state of	14/15/			
(iv) Halogen	0 4	10 85	90W.			11/25			
(v) Others LED	9 "	1		į.	.39				
a D. D. Late	9 W	10 NS	200 W						
2. Fan Points	3		-	34					
2 Dlug mainta /2	4.4								
3. Plug points (3-11)	12 5 6 13 - 0 5 0	1 77	600W.						
(i) 6 Amps	6 NY	100 m							
	1 K	1000 W	4000 W		1				
(ii) 16 Amps	4 16				ĺ	İ			
4. Electrical	3	100			1				
gadgets		163							
(i) Water Heater		ĺ							
(Geyser)					T (20)			18 11	
(ii) Refrigerator		2.7					1		
(iii) Air Conditioner		100	N. San					193	
(v) Others									
	rech til	1				4.7	100		
5. Welding						1 =7	1 1/4		
Transformer									
						va f	4		
6. Motor		11				1 3			