

Meghalaya Energy Corporation Limited

TEST REPORT

To certify that repaired/renewed/additional/new electric installation at the premises of

LLA-COUNTRYSIDE VIEW.

(Please leave one block between name & surname)

Full Name)

MAWDIANQDIANG SHILONG, MEAHA LAYA

(Address)

is duly completed, tested and is ready for your Engineer to test and connect on your main line.

I. The load has been arranged as follows :-

Details of Load	Wattage of each item	Phase - 1		Phase - 2		Phase - 3		Total watt of all 3 phases
		No. of points	Total watt	No. of points	Total watt	No. of points	Total watt	
1. Light points								
✓(i) Fluorescent	40 watts	6 nos	240 watts	x	16 Qtrs	=		3840 watts
(ii) Incandescent								5760 watts
✓(iii) CFL	20 watts	18 "	360 watts	x	16 Qtrs	=		
(iv) Halogen								9600 watts
(v) Others								
✓2. Fan points	100 watts	6 "	600 watts	x	16 Qtrs	=		11200 watts
3. Plug points (3-pin)								
✓(i) 6 Amps	100 watts	7 "	700 watts	x	16 Qtrs	=		48000 watts
✓(ii) 16 Amps	1000 watts	3 "	3000 watts	x	16 Qtrs	=		
4. Electrical gadgets								
(i) Water Heater (Geyser)								
(ii) Refrigerator								
(iii) Air Conditioner								
(iv) Others								
5. Welding Transformer								
6. Motor								
Total			4900 watts	x	16 No Qtrs	=		78400 watts
In case of load enhancement								
Existing load (in watts)								
Total load in the premises (in watts)			4900 watts					78400 watts

Notes :-

- (a) Details of any apparatus (other than the above mentioned) should be given.
 (b) Rating of capacitor used in Induction Motor and Welding Transformer (Test report of capacitor is to be enclosed).

KVAR