

Meghalaya Energy Power Distribution Corporation Limited

TEST REPORT

This is to certify that repaired/renewed/additional/new electric installation at the premises of

IADARISHA LYNQWA

(Please leave one blank between name & surname)

(Full Name)

JAI AWST JOSEPH SCHOOL SHILLONG

(Address)

is duly completed, tested and is ready for your Engineer to test and connect on your main line.

1 The load has been arranged as follows -

Details of Load	Wattage of each item	No. of points	Total Watt	No. of points	Total Watt	No. of points	Total Watt	Total watt of all 3 phases
1. Light points	9 watt	10 nos	90 watt					
(i) Fluorescent								
(ii) Incandescent	36 watt	2 nos	72 watt					
(iii) CFL								
(iv) Halogen								
(v) Others								
2. Fan points								
3. Plug points (3-pin)								
(i) 5 Amps	100 watt	2 nos	200 watt					
(ii) 15 Amps	1000 watt	2 nos	2000 watt					
4. Electrical gadgets								
(i) Water Heater (Geyser)								
(ii) Refrigerator								
(iii) Air Conditioner								
(iv) Others								
5. Welding Transformer								
6. Motor	746 watt	1 nos	746 watt					
Total			3 Kw					
In case of load enhancement								
Existing load (in watts)								
Total load in premises (in watts)								

Notes -

- Details of any apparatus (other than the above mentioned) should be given
- Rating of capacitor used in Induction Motor and Welding Transformer (Test report of capacitor is to be enclosed)



KVAR