

Meghalaya Power Distribution Corporation Limited

TEST REPORT

This is to certify that repaired/additional/ enhancement/ reduction new electric installation at the premises of

L A S H A I L I N P Y N G R O P E

(Please leave one block between name & surname)

(Full Name)

M A N P A T C I R C L E - 3

(Address)

is duly completed, tested and is ready for your Engineer to test and connect on your main line.

1. The load has been arranged as follows :-

Details of Load	Wattage of each item	Phase - 1		Phase - 2		Phase - 3		Total watt of all 3 phases
		No. of points	Total watt	No. of points	Total watt	No. of points	Total watt	
1. Light points (i) Fluorescent (ii) Incandescent (iii) CFL/LED Bulb (iv) Halogen (v) Others	20	15	300					
2. Fan points								
3. Plugs points (3-pins) (i) 6 Amps (ii) 16amps	100 1000	3 1	300 1000					
4. Electrical gadget (i) Water Heater (Geyser) (ii) Refrigerator (iii) Air Conditioner (iv) Others								
5. Welding Transformer								
6. Motor								
Total								
In case of load enhancement Existing load (in watt)								
Total load in the premises (in watt)								