Meghalaya Power Distribution Corporation Limited

TEST REPORT

This is to certify that/repaired/additional/ enhancement/ reduction/new electric installation at the premises of

SMTI BALARILINDA FSYLEM	
(Please leave one block between name & surname)	
(Full Name)	
MAWKASIANG (Address)	

is duly completed, tested and is ready for your Engineer to test and connect on your main line.

I. The load has been arranged as follows:-

Details of Load	Wattage of	Phase - 1		Phase - 2		Phase - 3		Total watt of
OI LOAQ	item	No. of points	Total watt	No. of points	Total watt	No. of points	Total watt	all 3 phases
1. Light points (i) Fluorescent (ii) Incandescent	100	4	400		3			
(iii) CFL/LED Bulb (iv) Halogen		į.	. 7					
(v) Others 2. Fan points			i i) of		
3. Plugs points (3-pins)			Lings	4-1				,
(i) 6 Amps (ii) 16amps	1000	9	2000			in the second se		
4. Electrical gadget	Ares O'C. VALUA							
Heater (Geyser) (ii) Refrigerator (iii) Air Conditioner	S MARBANLI Troni Shrenc Jo. No. 803	kH77. Elec	11-12 (1 ³⁴⁸) N	arat lakt		402-		
(iv) Others 5. Welding								
Transformer	* 4						j.	
6. Motor Total				10 10	1 3 1		ė .	
In case of load er	STATE OF THE PARTY		800 K	(WI		, (<u>X</u>)		
Existing load (in value) Total load in the watt)	premises (in	and the second						