

her stating  
ase and his  
supply of

# Meghalaya Power Distribution Corporation Limited

## TEST REPORT

This is to certify that/repaired/additional/ enhancement/ reduction/new electric installation at the premises of

SMTI BALARTILINDA FSYIEM

(Please leave one block between name & surname)

(Full Name)

MAWKASTANG

(Address)

is duly completed, tested and is ready for your Engineer to test and connect on your main line.

I. The load has been arranged as follows :-

Details of Load	Wattage of each item	Phase - 1		Phase - 2		Phase - 3		Total watt of all 3 phases
		No. of points	Total watt	No. of points	Total watt	No. of points	Total watt	
1. Light points (i) Fluorescent (ii) Incandescent (iii) CFL/LED Bulb (iv) Halogen (v) Others	100	4	400					
2. Fan points								
3. Plugs points (3-pins) (i) 6 Amps (ii) 16amps	100 1000	4 1	400 1000					
4. Electrical gadget (i) Water Heater (Geyser) (ii) Refrigerator (iii) Air Conditioner (iv) Others			1					
5. Welding Transformer								
6. Motor								
Total			1800 kwT					
In case of load enhancement Existing load (in watt)								
Total load in the premises (in watt)								