

Meghalaya Power Distribution Corporation Limited

TEST REPORT

This is to certify that repaired additional enhancement reduction new electric installation at the premises of

A I U S H A K H A R S O H T U N

(Please leave one block between name & surname)

(Full Name)

M A N P A T M A W M U R O K

(Address)

is duly completed, tested and is ready for your Engineer to test and connect on your main line.

I. The load has been arranged as follows :-

Details of Load	Wattage of each item	Phase - 1		Phase - 2		Phase - 3		Total watt of all 3 phases
		No. of points	Total watt	No. of points	Total watt	No. of points	Total watt	
1. Light points (i) Fluorescent (ii) Incandescent (iii) CFL LED Bulb (iv) Halogen (v) Others	10	60	600w					
2. Fan points								
3. Plug points (3-pins) (i) 6 Amps (ii) 16amps	4 1	60	240w 1600w					
4. Electrical gadget (i) Water Heater (Geyser) (ii) Refrigerator (iii) Air Conditioner (iv) Others								
5. Welding Transformer								
6. Motor								
Total	210		1840w					
In case of load enhancement Existing load (in watt)								
Total load in the premises (in watt)								