

Meghalaya Energy Corporation Limited

TEST REPORT

This is to certify that repaired/renewed/additional/new electric installation at the premises of

INJINSI DOKA MONGBRI

(Please leave one block between name & surname)

(Full Name)

SIBSING DONGSHILI CHAHI

(Address)

is duly completed, tested and is ready for your Engineer to test and connect on your main line.

The load has been arranged as follows :-

Details of Load	Wattage of each item	Phase - 1		Phase - 2		Phase - 3		Total watt of all 3 phases
		No. of points	Total watt	No. of points	Total watt	No. of points	Total watt	
1. Light points (i) Fluorescent (ii) Incandescent (iii) CFL (iv) Halogen (v) Others ^{9W} _{LED}	9W	10	90W					
2. Fan points								
3. Plug points (3-pin) ✓ 6 Amps ✓ 16 Amps	100W 1000W	8 2	200W 2000W					
4. Electrical gadgets (i) Water Heater (Geyser) (ii) Refrigerator (iii) Air Conditioner (iv) Others								
5. Welding Transformer								
6. Motor								
Total		2890W						
In case of load enhancement Existing load (in watts)								
Total load in the premises (in watts)		≈ 3KW						

Notes :-

- (a) Details of any apparatus (other than the above mentioned) should be given.
 (b) Rating of capacitor used in Induction Motor and Welding Transformer (Test report of capacitor is to be enclosed).

□ KVAR