Meghalaya Power Distribution Corporation Limited Test Report (LT Supply)

To,											
The Area Manager											
Lunjingshai, Shillong											
This is to certify that repaired/renewed/additional/new electric installation at the premises of											
Full name											
IBANRISHISHA MA	ωA										
(Please leave one block between name & surname)											
Address											
MAWKASZANG											

1. The load has been arranged as follows:

	Details of load	Wattag e of each	Phase I		Phase II		Phase III		Total wattage of all 3
1		item	No. of	Total	No. of	Total	No. of	Total	phases
			points	wattage	points	watt age	points	watta ge	
١	1. Light points								
	(i) Fluorescent								
	(ii) Incandescent								
1	(iii) GFL LED	1200	17	Joyn					
	(iv) Halogen		, ,						
	(v) Others								
	2. Fan points								
	3. Plug points (3-Pin)								
	(i) 6 Amps	1000	19	15004	4				
	(ii) 16 Amps	10000	3	30000	1				
	4. Electrical gadgets								
	(i) Water Heater (Geyser)	*							
	(ii) Refrigerator						<u> </u>		
	(iii) AC				1				
	(iv)Others								
	5. Welding transformer								
	6. Motor				. "				
	Total			47044	d				
	In case of load enhancement existing load (in watts)								