_
0
a
CUI
her
Der

Meghalaya Power Distribution Corporation Limited

TEST REPORT

This is to certify	hat/repaired/additional/enhancement/new electric installation at the	premises of
I III3 I3 to Certify	nay repaired, additional, email emeny new	•

I has is to certaly i	пат/герапес/асспиона/еппансетенунем сессите изавиатом и предоставления
ROSABELL	KHARKONGOR
(Full Name)	(Please leave one block between name & surname)

CIRCLE-I

is duly completed, tested and is ready for your Engineer to test and connect on your main line.

The load has been arranged as follows:-I.

	Wattage of	f Phase - 1		Phase - 2		Phase - 3		Total
Details of Load	each item	No. of points	Total watt	No. of points	Total watt	No. of points	Total watt	watt of all 3 phases
1. Light points (i) Fluorescent (ii) Incandescent (iii) LED (iv) Halogen (v) Others 2. Fan points	100	10	। करी					
3. Plugs points (3-pins) (i) 6 Amps (ii) 16amps 4. Electrical gadget (i) Water Heater (Geyser) (ii) Refrigerator (iii) Air Conditioner (iv) Others 5. Welding	100	6	600 1000		,			
Transformer 6. Motor	, ,							
Total *		260	okw					
In case of load enhancem Existing load (in wait) Total load in the premises								

Note:-

- (a) Detail of any apparatus (other than the above mentioned) should be given.
- (b) Rating of capacitor used in Induction Motor.