

Meghalaya Energy Corporation Limited

TEST REPORT

Assistant Executive Engineer
Service Connection Sub Division
Me.E.C.L. : Shillong

This is to certify that repaired/renewed/additional/new electric installation at the premises of

B I B I A N A N O N G D H A R

(Please leave one block between name & surname)

(Full Name)

M A N K A S I A N G

(Address)

is duly completed, tested and is ready for your Engineer to test and connect on your main line.

1. The load has been arranged as follows:-

Details of Load	Wattage of each item	Phase - 1		Phase - 2		Phase - 3		Total watt of all 3 phases
		No. of points	Total watt	No. of points	Total watt	No. of points	Total watt	
1. Light points	4/p, 10x60w,		600w					
(i) Fluorescent								
(ii) Incandescent								
(iii) CFL								
(iv) Halogen	8/p, 4x60w,		240w					
(v) Others								
			840w					
2. Fan points								
3. Plug points (3-pin)								
(i) 6 Amps								
(ii) 16 Amps			1kw					
4. Electrical gadgets								
(i) Water Heater (Geyser)								
(ii) Refrigerator								
(iii) Air Conditioner								
(v) Others								
5. Welding Transformer								
6. Motor								
Total	1kw							
In case of load enhancement at								
Existing load (in watt)								
Total load in the case (in watt)								

Remarks:-

(a) Details of any apparatus (other than the above mentioned) should be given.

(b) Rating of capacitor used in Induction Motor and Welding Transformer (Test report of capacitor is to be enclosed)

□ KVAR