## Meghalaya Power Distribution Corporation Limited

## TEST REPORT

This is to certify that/repaired/additional/ enhancement/ reduction/new electric installation at the premises of

SMTIDE	RIBIOI	N	KI	HA	IR	M	A 1.2	- k	II		I					
(Please leave one block between name & surname)																
(Full Name)			•													
TXNRING (Address)					I					L					Τ	

is duly completed, tested and is ready for your Engineer to test and connect on your main line.

I. The load has been arranged as follows:-

Details of Load	Wattage of cach	Phase - 1		Phase -	2	Phase	- 3	Total watt of		
r,	item	No. of points	Total watt	No. of points	Total watt	No. of points	Total watt	all 3 phases		
1. Light points (i) Fluorescent (ii) Incandescent (iii) CFLAED Bulb (iv) Halogen (v) Others	100	٧	400		*					
4							60			
2. Fan points 3. Plugs points										
(3-pins) (i) 6 Amps	100	4	400							
(ii) 16amps	[000]	2	2000							
4. Electrical gadget (i) Water Heater (Geyser) (ii) Refrigerator (iii) Air Conditioner (iv) Others										
5. Welding Transformer								Tops		
6. Motor				i i		-				
Total		9	8001	T						
In case of load Existing load ( Total load in t watt)	in watt)		0007	101						