

Meghalaya Power Distribution Corporation Limited

TEST REPORT

This is to certify that repaired/ additional/ enhancement/ reduction new electric installation at the premises of

EMILPA NONGSPUNG

(Please leave one block between name & surname)

(Full Name)

UMSALI

(Address)

is duly completed, tested and is ready for your Engineer to test and connect on your main line.

1. The load has been arranged as follows :-

Details of Load	Wattage of each item	Phase - 1		Phase - 2		Phase - 3		Total watt of all 3 phases
		No. of points	Total watt	No. of points	Total watt	No. of points	Total watt	
1. Light points (i) Fluorescent (ii) Incandescent (iii) CFL/LED Bulb (iv) Halogen (v) Others	9 w	5	45 wath					
2. Fan points								
3. Plugs points (3-pins) (i) 6 Amps (ii) 16amps	100 w 1000 w	3 1	300 wath 1000 wath					
4. Electrical gadget (i) Water Heater (Geyser) (ii) Refrigerator (iii) Air Conditioner (iv) Others			/					
5. Welding Transformer								
6. Motor								
Total			1345 wath					
In case of load enhancement Existing load (in watt)								
Total load in the premises (in watt)			2. K W					