

Annexure - 5

Meghalaya Power Distribution Corporation Limited Test Report (LT Supply)

To,
The
This is to certify that repaired/renewed/additional/new electric installation at the premises of
This is to certify that repaired/reflewed/additional/flew electric installation at the profiles of
Full name
BANCASPER MANLONG
(Please leave one block between name & surname)
Address
MANDIANGDIANG

1. The load has been arranged as follows:

Details of load	Wattag e of each item	Phase		Phase II		Phase III		Total wattage of all 3
		No. of points	Total wattage	No. of points	Total watt age	No. of points	Total watta ge	phases
1. Light points								
(i) Fluorescent								
(ii) Incandescent			*					
(iii) CFL/LED	9w	CONOS	90 W					
(iv) Halogen								
(v) Others								
2. Fan points	1 4							
3. Plug points (3-Pin)								
(i) 6 Amps	100 W	6NOX	600 W					
(ii) 16 Amps	1000W	2 NO8	2000 W					
Electrical gadgets								
(i) Water Heater (Geyser)								
(ii) Refrigerator								
(iii) AC								4
(iv)Others								
5. Welding transformer								
6. Motor								
Total			2690 W		-			
In case of load enhancement existing load (in watts)				· · · · · · · · · · · · · · · · · · ·				У -