cive from

Meghalaya Power Distribution Corporation Limited

TEST REPORT

This is to certify that/repaired/additional/ enhancement/ reduction/new electric installation at the premises of

,					•							
SMFIC	AT W	se leave	one blo	ock betw	Reen na	me & si	F	ne)	4			
(Full Name)		14					arrad,	iic)				
MAWLO (Address)	NB					İ						

is duly completed, tested and is ready for your Engineer to test and connect on your main line.

I. The load has been arranged as follows:-

Details of Load	Wattage of each	Phase - 1		Phase -	- 2	Phase	: - 3	Total watt of		
	item	No. of points	Total watt	No. of points	Total watt	No. of points	Total watt	all 3 phases		
1. Light points (i) Fluorescent (ii) Incandescent (iii) CFL/LED Bulb (iv) Halogen (v) Others 2. Fan points	20	10	Rev					i.		
3. Plugs points (3-pins) (i) 6 Amps (ii) 16amps 4. Electrical gadget (i) Water Heater	1000	504	500 400							
(Geyser) (ii) Refrigerator (iii) Air Conditioner (iv) Others	1 1111 - 1111 11111 11111 11111 11111 11111 11									
5. Welding Transformer										
6. Motor										
Total		490	00 W	וֹ			D:			
In case of load (Existing load (ir	n watt)	•				=				
Total load in th watt)	e premises (in	470	10 WA					N N		