

Meghalaya Energy Power Distribution Corporation Limited

TEST REPORT

This is to certify that repaired/renewed/additional/new electric installation at the premises of

SMTA-2 ALLAWKIMI MARTHA PAZET KHARJITHAN.

(Please leave one block between name & surname)

(Full Name)

LUMRUMNONH WAKHAP MAWPAT EAST KHASI HILLS

(Address)

SHILLONG.

is duly completed, tested and is ready for your Engineer to test and connect on your main line.

1. The load has been arranged as follows :-

Details of Load	Wattage of each item							Total watt of all 3 phases
		No. of points	Total Watt	No. of points	Total Watt	No. of points	Total Watt	
1. Light points (i) Fluorescent (ii) Incandescent (iii) CFL (iv) Halogen (v) Others	20W - 20 Nos 400W							
2. Fan points								
3. Plug points (3-pin) (i) 6 Amps (ii) 16 Amps	100W - 6 Nos. 600W 1000W - 4 Nos. 4000W							
4. Electrical gadgets (i) Water Heater (Geyser) (ii) Refrigerator (iii) Air Conditioner (iv) Others								
5. Welding Transformer								
6. Motor								
Total	5 KW		5000W					
In case of load enhancement Existing load (in watts)								