

# Meghalaya Energy Power Distribution Corporation Limited

## TEST REPORT

This is to certify that repaired/renewed/additional/new electric installation at the premises of

SMTI BLEND ELL. K. SOH KHELET

(Full Name)

(Please leave one block between name & surname)

ITSHYRWAT ITSHYRWAT SHILLONG 793012

(Address) EAST KASSI HILL MEGHALAYA.

is duly completed, tested and is ready for your Engineer to test and connect on your main line.

1. The load has been arranged as follows :-

Details of Load	Wattage of each item	No. of points	Total Watt	No. of points	Total Watt	No. of points	Total Watt	Total watt of all 3 phases
1. Light points LED	9 wt	15	135					
(i) Fluorescent								
(ii) Incandescent								
(iii) CFL								
(iv) Halogen								
(v) Others LED Tube	20 wt	8	160					
2. Fan points								
3. Plug points (3-pin)								
(i) 6 Amps	100 wt	7	700	10	1000	10	1000	
(ii) 16 Amps	1000 wt	1	1000	1	1000	1	1000	
4. Electrical gadgets								
(i) Water Heater (Geyser)								
(ii) Refrigerator								
(iii) Air Conditioner								
(iv) Others								
5. Welding Transformer								
6. Motor								

6 kw