

Meghalaya State Electricity Board

TEST REPORT

This is to certify that repaired/renewed/additional low electric installation at the premises of

ARTILIM ROW THANGMAH GW

(Please leave one block between name & surname)

(Full Name)

COUNTRYSIDE NEW MAWDIAMADIANH, Shillong

(Address)

is duly completed, tested and is ready for your Engineer to test and connect on your main line.

1. The load has been arranged as follows

Details of Load	Wattage of each item	Phase - 1		Phase - 2		Phase - 3		Total watt of all 3 phases
		No. of points	Total watt	No. of points	Total watt	No. of points	Total watt	
1. Light points (i) Fluorescent (ii) Incandescent (iii) CFL (iv) Halogen (v) Others	40W	7	280	7	280	7	280	840
2. Fan points								
3. Plug points (3-pin) (i) 6 Amps (ii) 16 Amps	100W 500W	2 1	200 500	2 1	200 500	2 1	200 500	600 1500
4. Electrical gadgets (i) Water Heater (Geyser) (ii) Refrigerator (iii) Air Conditioner (v) Others								
5. Welding Transformer								
6. Motor								
Total	3kW		980		980		980	2940
In case of load enhancement								
Existing load (in watts)								
Total load in the premises (in watts)								

Notes

- Details of any apparatus (other than the above mentioned) should be given.
- Rating of capacitor used in Inductive Motor and Welding Transformer (Test report of capacitor is to be enclosed)

KVAR