

Meghalaya State Electricity Board

TEST REPORT

The Assistant Executive Engineer
Service Connection Sub-Division
MeSEB, Shillong

This is to certify that repaired/renewed/additional/new electric installation at the premises of

INIHASNI NA NADEM

(Full Name)

DIENGPASOH EKHD (Address)
is duly completed by me

(Address)

is duly completed, tested and is ready for your engineer to test and connect on your main line.

1. The load has been arranged as follows:-

Details of Load	Wattage of each item	Phase - 1		Phase - 2		Phase - 3		Total Watt of all 3 Phases
		No of Points	Total Watt	No of Points	Total Watt	No of Points	Total Watt	
1. Light points <u>LED</u>	200	10 nos	200w					
i. Fluorescent								
ii. Incandescent								
iii. CFL								
iv. Halogen								
v. Other								
2. Fan Points	600	5 nos	300w					
3. Plug Points (3-pin)								
i. 6 Amps	1000w	5 nos	500w					
ii. 16 Amps	1000w	1 no.	1000w					
4. Electric gadgets								
i. Water heater. (Geyser)								
ii. Refrigerator								
iii. Air Conditioner								
iv. Others								
5. Welding								
Transformer								
6. Motor								
Total			2000w					
In case of load enhancement existing load (in words)			1					
Total load in the premises (in watts)			2000w					

Notes: -

- (a) Details of any apparatus (other than the above mentioned) should be given.
- (b) Rating of capacitor used in induction Motor and Welding Transformer (Test report of capacitor is to be enclosed)

2KW KVAR