

Meghalaya Energy Power Distribution Corporation Limited

TEST REPORT

This is to certify that repaired/renewed/additional/new electric installation at the premises of

THELRI DA PYNGROPE
 (Please leave one block between name & surname)

(Full Name)

MAWRAT CIRCLE 11 B

(Address)

is duly completed, tested and is ready for your Engineer to test and connect on your main line.

1. The load has been arranged as follows -

Details of Load	Wattage of each item							Total watt of all 3 phases
		No. of points	Total Watt	No. of points	Total Watt	No. of points	Total Watt	
1. Light points								
(i) Fluorescent								
(ii) Incandescent								
(iii) CFL	20	15	300					
(iv) Halogen								
(v) Others								
2. Fan points								
3. Plug points (3-p n)								
(i) 6 Amps	100	4	400					
(ii) 16 Amps	1000	1	1000					
4. Electrical gadgets								
(i) Water Heater (Geyser)								
(ii) Refrigerator								
(iii) Air Conditioner								
(iv) Others								
5. Welding Transformer								
6. Motor								
Total			1700					
In case of load enhancement								
Existing load (in watts)								
Total load in premises (in watts)			2 kw					

Notes

- (a) Details of any apparatus (other than the above mentioned) should be given
- (b) Rating of capacitor used in induction Motor and Welding Transformer (Test report of capacitor is to be enclosed).



KVAR