

MECHALAYA ENGINEERING CORPORATION LTD

TEST REPORT.

This is to certify that repaired/renewed/added new electric installation at the premises of

SYRPAJ LIN ZONA G WANNIANG

(Please leave one block between name & surname)

(Full name)

MAWKASIAN G

(Address)

is duly completed, tested and is ready for your Engineer to test and connect on your main line.

1 The load has been arranged as follows :-

Details of Load	Wattage of each item	Phasi - 1		Phasi - 2		Phasi - 3		Total Watt of all 3 phases
1. Light Points								
(i) Fluorescent								
(ii) Incandescent								
(iii) CFL								
(iv) Halogen								
(v) Others <i>led</i>	<i>10 W.</i>	<i>10</i>	<i>100 W</i>					
2. Fan Points								
3. Plug Points (3-pin)								
(i) 6Amps	<i>100 W</i>	<i>5</i>	<i>500 W</i>					
(ii) 16Amps	<i>1000 W.</i>	<i>1</i>	<i>1000 W</i>					
4. Electrical gadgets								
(i) Water Heater (geyser)			<i>/</i>					
(ii) Refrigerator								
(iii) Air Conditioner								
(iv) Other								
5. Welding Transformer								
6. Motor								
Total			<i>1600 W</i>					
In case of load enhancement								
Existing load (in watts)								
Total load in the premises (in watts)			<i>2 Kw</i>					

Notes :-

(a) Details of any apparatus (other than the above mentioned) should be given.

(b) Rating of capacitor used in Induction Motor and Welding Transformer (Test report of capacitor is to be enclosed)