



BANGALORE ELECTRICITY SUPPLY COMPANY LIMITED
 (ಬೆಂಗಳೂರು ವಿದ್ಯುತ್ ಸರಬರಾಜು ಕಂಪನಿ ನಿಗಮಿತ್)

Office of the
 Meter Testing Sub Division
 C, O&M Division, BESCOM

34400

INSPECTION REPORT OF R R No. / ACCOUNT ID No.
 DATE OF INSPECTION Name & Designation of Inspecting Officer.

1. Name of the Consumer : 22/1/156
 2. Address : AV 11, LT. Pabing Nagadi

3. Sanctioned Load : SLV 7.5 KW on Parallel Bank
 4. Tariff : Madiganahalli, INKW/Reed

5. METER DETAILS

a) Make	3 Phase / 1 Phase		Volts	Amps
	Phase	Phase		
b) Sl. No.	R	R
c) Capacity	LEG		Y	248.5
d) Reading at the time of inspection CKWH	E	14110
e) Condition of the Meter	B	248.2
	Pr Kw	26.8
	Pr Pf	0.94

Recording / Not Recording / MNR / MBO / OTHERS : Recording / Not Recording / MNR / MBO / OTHERS

6. DETAILS of SEALS
 a) Meter Main Cover Seal : Provided / Not Provided /
 b) Terminal Cover Seal : Provided / Not Provided /

7. Reading History

Description	Cumulative	Bill				
		Bill - 1	Bill - 2	Bill - 3	Bill - 4	Bill - 5
kwh						
MD in (kw)	6059.3	5314	5818	5484	5504	5057
PF	0.52	0.54	0.54	0.54	0.54	0.55

9. REMARKS : Sl. No. 156 - KMDA Pilsol SA. Ct. 1. W. 3. 78
R-988740, V. 355771, R. 355939, W. 35942
When tested and found that consumer fixed relay make
sols. Pilsol circ. for relay control meter, in software control share.
Bad in stand for [10] terminal missing. Hence meter get
as per BS-5759 norms.

Name and Signature of the Consumer /
 Representative Present at the time of Inspection
 Name & Signature of the Inspecting
 Officer with Designation

- Copy Submitted to :
- The Executive Engineer (EI.) : BESCOM (C,O&M Division), BESCOM.
 - The Assistant Executive Engineer (EI.), (C,O&M Sub Division), BESCOM.
 - Consumer :
 - O/C Assistant Engineer (EI.) / Junior Engineer (EI.) C, O & M, Section.....